

Michael O. Leavitt

Kathleen Clarke

Executive Director

Lowell P. Braxton

Division Director

Governor

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

INSPECTION REPORT

| Partial: XXX Complete: | Exploration: |
|--------------------------|--------------|
| Inspection Date & Time: | <u> </u> |
| Date of Last Inspection: | 06/12/2001_ |

| Mine Name: Deer Creek Mine County: Emery | Permit Number: |
|---|-------------------|
| Permittee and/or Operator's Name: PacifiCorp | |
| Business Address: P.O. Box 310, Huntington, Utah 84528 | |
| Type of Mining Activity: Underground XXX Surface | Prep. Plant Other |
| Company Official(s): <u>Ken Fleck</u> | |
| State Official(s): <u>Stephen J. Demczak</u> Federal Official(s): <u>None</u> | |
| Weather Conditions: Warm, 90's | |
| Existing Acreage: Permitted 18,866 Disturbed 95.79 Regularity | raded Seeded |
| Status: Active XXX | · |

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

| | | EVALUATED | N/A | COMMENTS | NOV/ENF |
|-----|---|-------------------|--------|-----------|--------------|
| 1. | PERMITS, CHANGE, TRANSFER, RENEWAL, SALE | | | П | П |
| 2. | SIGNS AND MARKERS | | П | | |
| 3. | TOPSOIL | $\overline{\Box}$ | П | П | \Box |
| 4. | HYDROLOGIC BALANCE: | | | | |
| | a. DIVERSIONS | [X] | П | [X] | \Box |
| | b. SEDIMENT PONDS AND IMPOUNDMENTS | | \Box | П | \Box |
| | c. OTHER SEDIMENT CONTROL MEASURES | [X] | П | [X] | \Box |
| | d. WATER MONITORING | [X] | \Box | [X] | , <u>[</u>] |
| | e. EFFLUENT LIMITATIONS | \Box | П | Ц | \Box |
| 5. | EXPLOSIVES | Ц | \Box | П | \Box |
| 6. | DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES | Ц | \Box | П | \Box |
| 7. | COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS | \Box | \Box | \square | \Box |
| 8. | NONCOAL WASTE | [X] | П | [X] | \Box |
| 9. | PROTECTION OF FISH, WILDLIFE AND RELATED | | | | |
| | ENVIRONMENTAL ISSUES | Ц | \Box | | \Box |
| 10. | SLIDES AND OTHER DAMAGE | П | \Box | Ц | |
| 11. | CONTEMPORANEOUS RECLAMATION | Ц | \Box | | \Box |
| 12. | BACKFILLING AND GRADING | П | \Box | \Box | \Box |
| 13. | REVEGETATION | П | П | \Box | Ц |
| 14. | SUBSIDENCE CONTROL | Ц | \Box | \Box | \Box |
| 15. | CESSATION OF OPERATIONS | Ш | \Box | \Box | \Box |
| 16. | ROADS: | | | | |
| | a. CONSTRUCTION/MAINTENANCE/SURFACING | Ш | \Box | \Box | Ц |
| | b. DRAINAGE CONTROLS | П | \Box | | П |
| 17. | OTHER TRANSPORTATION FACILITIES | | \Box | | Ц |
| | SUPPORT FACILITIES/UTILITY INSTALLATIONS | [X] | \Box | [X] | Ц |
| | AVS CHECK (4th Quarter- April, May, June) | | П | Ц | · [] |
| 20. | AIR QUALITY PERMIT | \Box | \Box | | П |
| 21 | PONDING & INSUDANCE | [] | [] | [] | [] |

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/015/018

DATE OF INSPECTION: <u>07/06/2001</u>

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

4A. HYDROLOGIC BALANCE: DIVERSIONS

Several diversions were spot-checked and complied with the R645 Coal Rules. No water was flowing during the inspection.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Sediment structures were inspected at Deer Creek and Rilda Canyon. Siltation structures consisted of silt fences and dugout ponds. All structures were maintained as required by the R645 Coal Rules and the Mining and Reclamation Plan.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The first quarter water monitoring was reviewed at the office prior to inspection. The inspection consisted of reviewing all water monitoring sites, and cross-checking parameters with the Mining and Reclamation Plan. Mr. Fleck was not asked any information about second and third quarter water monitoring because Mr. Fleck is not assigned these duties. The personnel assigned to these duties were either at a meeting or on vacation. A follow-up discussion will be made on the next inspection.

8. NONCOAL WASTE

There was a small amount of non coal waste material at the Deer Creek Mine, located by the substation. The permittee has committed to picking-up and storing the material in the designated area.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

The Rilda Canyon disturbed area was inspected. The permittee has not started the construction of the concrete pad. The purpose of the pad is to unload longwall equipment. However, work was being performed by moving longwall pan-line underground.

Inspector's Signature:

Stephen J. Demøzak

Date: <u>July 9, 2001</u>

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM

Chuck Semborski, PacifiCorp

Price Field office

O:\015018.DER\Compliance\2001\p 0706.wpd